
Swing damper BRM10-73-01



13.07.2017



Greasing must be repeated after every 8 working hours of the link.